

Three Phase Induction Motors – Torque-Slip Characteristics & Related Problems

Contents :

- ❖ Torque slip characteristics
- ❖ Power flow diagram
- ❖ Relationship between rotor power and losses
- ❖ Related Problems

Torque-Slip Characteristics


- The curve drawn between torque and slip from start ($s=1$) to Synchronous speed ($s=0$) is called torque slip characteristics of the induction motor
- **Torque Equation**
- **Input voltage is constant ($E_2=C$)**

$$T \propto \frac{sE_2^2 R_2}{R_2^2 + (sX_2)^2}$$

$$T \propto \frac{sR_2}{R_2^2 + (sX_2)^2}$$

2

Torque-Slip Characteristics



Torque-Slip Characteristics

- **Three Regions:**

- Stable operating region
- Unstable operating region
- Normal operating region

- *Stable Region (AB)*

- 's' is very small (then, $(sX_2)^2 \lll R_2^2$), Hence $s^2X_2^2$ is neglected

$$T \propto \frac{sR_2}{R_2^2} \propto s \text{ [as } R_2 = \text{Constant]}$$

- in this region as **load** \uparrow , **T** \uparrow , **s** \uparrow
- Characteristics is approximately **straight line**

4

Torque-Slip Characteristics

- *Unstable Region (BC)*

- When s increases further from s_m the region is unstable region, s is high (between s_m and 1), R_2^2 can be neglected as compared to $s_2 X_2^2$

$$T \propto \frac{s}{(sX_2)^2} \propto \frac{1}{s} \text{ [as } X_2 = \text{Constant]}$$

- in this region as **load** \uparrow , $s \uparrow$, $T \downarrow$
- Characteristics is approximately **rectangular hyperbola**.
- When **load further increases**, $N \downarrow$, $s \uparrow$, leads motor to **standstill condition**, hence motor should not be operated at any point in this region.

5

Torque-Slip Characteristics

- **Normal Region (AD)**
 - Low slip region, the motor can continuously operated in this region.
- **Three torques:**
 - Starting torque (T_{st})
 - Maximum torque or pull out torque (T_m)
 - Full load torque (T_{fl})
- **Starting Torque (T_{st})**
 - The motor produces the torque when $s=1$ speed is zero.
- **Maximum Torque or Pull out Torque (T_m)**
 - The torque produced at $s=s_m$ is called maximum torque.
 - s_m is slip at which maximum torque occurs.
 - Also called **breakdown torque of pull out torque.**
- **Full Load Torque (T_{fl})**
 - In the characteristics the torque corresponding to point D is called full load torque of motor. usually $T_{fl} < T_m$.

6

Torque-Slip Characteristics

Eddy Current Losses

- Occur due to flow of eddy current through body of the stator core.
- Can be minimized by using laminated construction of the stator core
- Two losses are depend on supply frequency ,
- $f_{\text{stator}} = f_{\text{supply}}$, hence iron loss for stator is more
- $f_{\text{rotor}} \ll$, hence iron losses are also very small, neglected under running condition

Mechanical Losses

- Consists of frictional losses and windage losses
- Losses are $\ll\ll$ due to speed drop is very small
- Constant losses = Iron Losses + Mechanical Losses


Electrical Losses

- Due to resistance of stator and rotor winding. (stator and rotor copper losses)
- When load \uparrow current \uparrow , so it is called variable losses

$$\text{Rotor Copper Losses} = 3I_2^2 R_2$$

7

Power Flow Diagram



8

Power Flow Diagram

- Induction motor converts electrical power into mechanical power.
- 3ph supply is fed to stator, **input power** P_{in} is
$$P_{in} = \sqrt{3}V_L I_L \cos \varphi$$
- Losses occur in stator called **stator losses** (P_{SL})
- Remaining power is transferred to rotor magnetically,
- It is called output of the stator or **input to the rotor** (P_2)
$$P_2 = P_{in} - P_{SL}$$
- In rotor side, **rotor copper losses** occur (P_{cu}).
- Normally rotor iron losses are very small therefore it should be neglected.
- Remaining part is called **mechanical power developed** (P_m)

$$P_{cu} = 3I_2^2 R_2$$

$$P_m = P_2 - P_{cu}$$

9

Power Flow Diagram

- Due to rotating part in motor **mechanical losses** (P_{mL}) occur.

$$P_{out} = P_m - P_{mL}$$

$$\text{Rotor Efficiency} = \frac{\text{Rotor Output}}{\text{Rotor Input}} = \frac{P_m}{P_2}$$

$$\text{Motor Efficiency} = \frac{\text{Mechanical power Output at shaft}}{\text{Electrical power Input to the stator}} = \frac{P_{out}}{P_{in}}$$

10